




**THE NEXT GENERATION
OF QUALITY CONTROL!**

SAMPLING OF HMA MIX

The key to accurate test results is to obtain a representative sample.

Most state DOTs require sampling out of a truck at the plant.

How can this be done consistently and safely?



*IN THE PAST LOADING WAS ONE DROP
NOW TO MINIMIZE SEGREGATION 3
DROPS ARE USED*



WHERE DO YOU SAMPLE?



DO YOU WANT YOUR QC TECH TO DO THIS?



OR THIS?



WHAT IS THE SOLUTION?

- TO BE SAFE
- TO SECURE THE PROPER QUANTITY OF MIX FOR TESTING
- TO GET A REPRESENTATIVE SAMPLE FROM A TRUCK
- TO BE ABLE TO ADAPT TO ANY SIZE LOAD OR TRUCK CONFIGURATION



*INTRODUCING
THE T-REX SAMPLER*



*SAMPLER CAN BE
POSITIONED OVER TRUCK*



*PICK YOUR SPOT
INSERT INTO MIX*



OPEN THE JAWS





PUSH DOWN AND CLOSE



DEPOSIT INTO SPLITTER





2007 SEAUPG CONFERENCE-SAN ANTONIO, TEXAS

